





Model 3020 OPTOMIZER® Coating Streak/Scratch Inspection Technology












EQUIPMENT PICTORAL Model 3020 OPTOMIZER® Coating Streak Inspection Technology





R.K.B. OPTO-ELECTRONICS, INC.

6677 Moore Road • Syracuse, New York • 13211 • United States of America
Tel: +001-315-455-6636 • Fax: +001-315-455-8216 • Email: sales@rkbopto.com
Internet: www.rkbopto.com / www.webinspection.us / www.hole-detection.com

Model 3020 OPTOMIZER® Coating Streak/Scratch Inspection Technology



Events								
PCode	Reel	Class	ID	Date	Date	Type	Motor	CH
	1	3	2307	11/01/1999 10:31:40	ASMO	ASMO	0	0
	1	3	6604	11/01/1999 7:44:20	ASMO	ASMO	0	0
	1	3	3321	11/01/1999 2:01:24	PSM	PSM	0	0
	1	3	7526	11/01/1999 9:40:17	ASMO	ASMO	0	0
	1	3	7403	11/01/1999 7:31:27	ASMO	ASMO	0	0
PCode	Reel	Class	ID	Date	Date	Type	Motor	CH
	1	3	6010	11/01/1999 2:32:11	PSM	PSM	0	0
	1	3	6602	11/01/1999 2:52:38	PSM	PSM	0	0
	1	3	7526	11/01/1999 1:48:30	PSM	PSM	0	0
	1	3	7530	11/01/1999 2:02:21	PSM	PSM	0	0
PCode	Reel	Class	ID	Date	Date	Type	Motor	CH
	1	3	6615	11/01/1999 2:46:03	PSM	PSM	0	0
	1	3	6616	11/01/1999 2:46:03	PSM	PSM	0	0



R.K.B. OPTO-ELECTRONICS, INC.

6677 Moore Road • Syracuse, New York • 13211 • United States of America
 Tel: +001-315-455-6636 • Fax: +001-315-455-8216 • Email: sales@rkbopto.com
 Internet: www.rkbopto.com / www.webinspection.us / www.hole-detection.com